
LOW EXPANSION GLAZE
Firing Chart

	LOW EXPANSION GLAZE
Dry out, min	4.0
Insertion Temperature °C	500
Heat rate ° C / min.	80
Vacuum start	No vacuum
Vacuum stop	
Firing Temperature °C	900°C
Hold Time, min	1.0